


Surveyed by John J. Henders Surveyor of Clay County Indiana Vday the 26th and 27th 1887 After ten dayes Notice being given to M.W. Perkins John Gibbens Wm Buckalew D. H. Davis and Charles Wolfgang by Allen Gibbens then being the parties interested M.W. Perkins and Jefferson Stavett Chairman Wm Buckalew flagman Sworn as the law requires and corners set from 1 to 16



Cor No 1 Lime Stone 14 in long Marked A with broken Glass under it
 = = 2 = = = 14 in long = = X = = = =
 Corner No 2 is 1.11 chains west of Cor No 1
 Cor No 3 Lime Stone 12 in long ^{marked H} broken Glass under it
 = = = is 1.74 chains west of Cor No 2
 Cor No 4 Lime Stone 15 in long Marked T Broken Glass under it
 = = = is South 42 degrees west of No 3. 2.46 chains
 Cor No 5 Lime Stone 17 in long A small hole in the side 5 in from ^{top}
 = = = is North 87 degrees west 5.71 chains from No 4
 Cor No 6 Sand Stone 13 in long Marked X With Broken Crockery under ^{it}
 = = = is in line with 4 and 5
 Cor No 7 Sand Stone 15 in long Marked W Broken Glass under it
 from which a Sand Stone 14 in long is North 30 links
 Cor No 8 Nigger head Stone 14 x 18 in Glass under it
 Sand Stone 6 in North 27 links
 Cor No 9 Nigger head Stone 18 in long Glass under it
 Sand Stone 8 in long is S 45 W 43 links
 = = = 7 1/2 = = = N 45 E 37 = =

See Old Record
 Page 100